

# Product Bulletin

Issue no. 26 / January 09


## PM Information: 500 Series Rotor Bearing Improvements

The new rotor bearings are installed in the following machines from factory:

Starting with 57800771

Starting with 57900450

For the new rotor bearing CLAAS Engineers redesigned the flow of grease into the bearing as shown in the drawing below.



CLAAS Kit number 173 630.3

Please refer to the LEXION Connection for any Service Bulletins for further information